FIELD Environmental Instruments

Equipment Rental and Field Supplies

"Your Needs Are Our Business"

Toll-Free 800-393-4009



SPECIFICATIONS

Take temperature and humidity measurements both indoors and out! Choose from two meters. One model reads dewpoint, relative humidity and temperature, the economical model

reads relative humidity and temperature.

These microprocessor-based meters have push-button operation for max/min memory storage, memory, high and low setpoint audible alarms for temperature and RH, hold and °F/°C readout. Kit includes meter, probe, 33% RH and 75% RH calibration salt (NIST traceable) bottles, four 1.5 V AA batteries, hard plastic carrying case and operating instructions.

FEATURES

Meter's dual display shows humidity and temperature MAX/MIN memory recall function Push-button two-point auto-calibration High/low set point alarms Analog recorder output to create hard copies of your data

Humidity Resolution: 0.1% RH Humidity Accuracy: ±2% from 0 to 95% RH at room temp., ±3% from 95 to 100% RH

Humidity Output: 0 to 1 V, 10 mV / 1% RH Humidity Sensor: electronic capacitance polymer film Humidity Response time:ten seconds (90% response) Dewpoint Range:-51.0 to 49.0°C (-60.0 to 120.0°F) Dewpoint Resolution: 0.1°C or °F Dewpoint Accuracy: ±2.0°C (±4.0°F) Dewpoint Sensor: electronic capacitance polymer film

Dewpoint Output: 0 to 1 V, 10 mV / 1% RH

Dewpoint Response time:ten seconds (90% response)

Temperature Range: 0.0 to 50.0° C (32.0 to 122.0° F)Temperature Resolution: 0.1° C or $^{\circ}$ FTemperature Accuracy: $\pm 0.6^{\circ}$ C ($\pm 1.0^{\circ}$ F)Temperature Sensor: thermistor typeTemperature Output: 0 to $2 \vee, 40 \text{ mV/}^{\circ}$ C (10 mV/° F)Temperature Response time: one minuteTemperature limits: 0.0 to 50.0° C (32.0 to 122.0° F) for RH readingsDisplay: dual LCDPower: $4 \times 1.5 \vee$ AAA batteries, 50 hours continuous useDimensions: $7.5^{\circ} \times 3.5^{\circ} \times 1.75^{\circ}$ ($19 \times 9 \times 4.5$ cm)Shipping weight: 4 lb (1.8 kg)

99 Miller Avenue

OAKTON

Thermohygrometer Kit

Braddock, PA 15104

800-393-4009

Fax412-271-5083

info@ fieldenvironmental.com

Visit us soon on the web www. fieldenvironmental.com

Inquiries and orders 800-393-4009



| | Humidity | Temperature | Dewpoint (WD-35612-10 only) |
|------------|---|----------------------------------|-----------------------------------|
| RANGE | 0 to 99.9% RH | 0.0 to 50.0 C 32.0 to 122.0 F | -51.0 to 49.0 C -60 to 120.0 F |
| RESOLUTION | 0.1% RH | ± 0.1 C or F | ± 0.1 C or F |
| ACCURACY | ±2% from 0 to95% Rh at room temperature; ± 3% from 95 to 99.9 %RH | ±0.6 C ±1.0F | ± 2.0 C ± 4.0 F |
| SENSOR | electronic capacitance polymer film | thermistor-type | |